Lab 11/12 Presentation ECEN 3730

Connor Sorrell

<u>Introduction</u>

In this lab, we measure the resistance of 4 traces of different widths, and then attempt to blow one up.


- We first apply the concept of sheet resistance in order to estimate the resistance of the traces using the 'square' method
- We then use the 2 wire method using the DMM
- We then perform a 2 wire null-method, where we compare to a reference resistance (similar to zeroing a scale)
- We then sweep a constant current through the traces, and observe the voltage drop on the DMM to find the resistance using the 4 wire method



For 1oz copper, $R = 0.5 \text{m}\Omega/\text{square}$

Line Width	# Of Squares	R (Estimate)	2 Wire	2 Wire (null)	4 wire
6 mil	1000 / 6 = 166.7	166.7 * 0.5 mΩ = 83mΩ	150 mΩ	70 mΩ	83 mΩ
10 mil	1000 / 10 = 100	100 * 0.5 mΩ = 50mΩ	115 mΩ	35 mΩ	47 mΩ
20 mil	1000 / 10 = 50	50 * 0.5 mΩ = 25mΩ	91 mΩ	11 mΩ	23 mΩ
100 mil	1000 / 100 = 10	10 * 0.5 mΩ = 5mΩ	75 mΩ	4 mΩ	6.5 mΩ

4 Wire Measurement:	Current supplied (A) (CC Mode)	DMM Reading (mV)	Resistance (m Ω)
6 mil	1A	83 mV	83 mΩ
10 mil	1A	47 mV	47 mΩ
20 mil	1A	23 mV	23 mΩ
100 mil	1A	6.5 mV	6.5 mΩ




Blowing up Trace

To blow up the 6 mil trace, I first started with the Saturn PCB Tool, which calculated that for a 120°C (216°F) increase in temperature, I would need to source 1.8 A through the trace.

- Knowing this, I started with 2 A. After around 30 seconds, I could begin to feel the trace get hot.
- I then ramped the current to 3 A, and felt the temperature rise even further.
- At 4 A, the trace took roughly 10 seconds to begin burning and eventually blow entirely.
- As the trace heated up, the voltage increased due to thermal loss (increase in resistance)

I then repeated this method for the 100 mil trace, testing up to 10 A, the limitation of the power supply. In this case, the trace never blew up.



Conclusion

- Trace resistance is easy to estimate using just geometry and known sheet resistance.
- Two wire measurements are fast but include loop resistances, which affects the accuracy for small resistance values
- Four wire measurements are essential for accurate readings of small resistances because they remove the influence of loop and contact resistance
- Using a constant current source simplifies resistance calculations and allows easy validation of theoretical predictions.
 - Using the 4 wire method on the DMM even further drastically simplifies the measurement

6 mil trace took roughly ~4 A to blow, where as 10 A could not blow up the 100 mil trace.